| STATE                              | COUNTY  | TOWN OR VICINITY   |
|------------------------------------|---|--|
| MASS.                              | Plymouth  | Hingham 🗸  |
| INDEX NUMBER MASS, 12-HING 13      | MONUMENT Samuel Lincoln Cottag  | 182 North St.<br>ge  |
| REPRESENTED IN<br>NEGATIVE FILE    | Description - Frame with wood siding. The original cottage lat rear with gable roof. 1 chimney.  History - Samuel Lincoln (c 1619-1690) son of Edward Lincoln of Hingham, Norfolk County, |  |
| PUBLISHED<br>PHOTOGRAPHS           |   |  |
| PUBLISHED<br>DRAWINGS              |   |  |
| England, emigrate 2 elder brothers |   | d to America in 1637 with<br>and settled at Hingham,<br>is son and grandsom, |
| <b>ero</b> 6 <del>8</del> 369      | Mordecai were on fou  | anders. Mordecai<br>(over)<br>N BUILDINGS SURVEY                             |

and the second second section of the second section of the second second

(cont a)

(1686-1736) moved to Chester County, Pa. His son John (1711-1773), a weaver settled in Rockingham County Virginia. His son Abraham settled in Kentucky, in 1780, and was killed by Indians in 1784. His son Thomas \$1778-1851), born in Augusta County, Va. (now Rockingham) married Nancy Hanks (1783-1818) of Virginia, June 12. 1806 in Washington County, Kentucky. Their son Abraham 16th President of the United States was born on Rock Spring Farm, 3 miles from Hodgenville in Hardin (now Larue) County, Kentucky, February 12, 1809.

Author of Card
Thomas R. Jones, Architect
HABS - Nat'l Park Service
10/6/58